OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

| Date of Test | 8-27-03 | Operator <u>M&G Drillin</u> | ng Company | AP1 #30-0 | 45-21735 | |
|-----------------|----------------------------|---------------------------------|-----------------------|--|----------------------|---------------------------------------|
| Property Name | HAMMONI | Well No 55 | A Location: Unit 1 | Section 26 | Township2 | Range 8W |
| Well Status (Si | nut-In or Producing | Tubing 52 | Intermediate// | 4 Casing <u>168</u> | Bradenhead | 0 |
| OPEN | BRADENHEAD AN | ND INTERMEDIATE | TO ATMOSPHERE | INDIVIDUALLY | FOR 15 MIN | UTES EACH |
| TIME | PRESSURES: INTERMEDIATE | CASING | | 1 | BRADENHEAD FLOWED | INTERMEDIATE FLOWED |
| 5 minutes | NA | 168 | Steady Flow | <u> </u> | thing | NA |
| 10 minutes | | 168 | Surges | | | |
| 15 minutes | | 168 | Down to Nothing | | | |
| 20 minutes | | | Nothing | | | · · · · · · · · · · · · · · · · · · · |
| 25 minutes | | | Gas | | 220 75 (11 (11)2) | |
| 30 minutes | | | Gas & Water | | 005 | |
| | | | Water | - (52) - (52) - (52) | 2005 | <u> </u> |
| If bradenhead | flowed water, check all | of the descriptions that | t apply below: | | | J |
| CLEAR _ | FRESH | SALTY_ | SULFUR | BLACK | <u> </u> | |
| 5 MINUTE SE | IUT-IN BRADENHE | AD C | ntermediate <u>//</u> | <u>A</u> rmonijongš | mente e elektris | |
| REMARKS: | unit e l'art | | | a yan da | | |
| | | | | | | |
| ··· | | | | | · | |
| | 9 1/0 | V. 16.00 | | | | |
| Ву | Pumper | Vincon Wit | tness | | | |
| | (Positio | n) | | | | |