OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 10-15-03 Operator M&G Drilling Company API #30-0 45-22577						
Property Name	HAMMON	Well No	41R Location: Unit G	Section 25	Fownship 2	7N Range 8W
Well Status (Shut-In or Producing) Tubing 12 Intermediate NA Casing 68 Bradenhead 0						
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME	PRESSURES: INTERMEDIATE	CASING		BR -	ADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	NA	68	Steady Flow	Not	hine	NA
10 minutes		68	Surges-			
15 minutes		68	Down to Nothing	J. 100 (100 (100 (100 (100 (100 (100 (100		
20 minutes			Nothing			
25 minutes			Gas		52	62720 A 33
30 minutes			Gas & Water		007	2003
			Water			
If bradenhead flowed water, check all of the descriptions that apply below:						
CLEAR	FRESH	SALTY	SULFUR	BLACK		
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE						
REMARKS:						
By _	Dani/24	vízen v	Vitness			
	Pumpe	Vison_ V				· · · · · · · · · · · · · · · · · · ·
	/ (Position					