OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

## BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	8-27-03	Operator M&G Drilling	g Company	API	#30-0 <u>45-23579</u>	
Property Name	HAMMON	ND Well No. 92	Location: Unit_	O Section	25 Township	27N Range 8W
Well Status (Sb	ut-In or Producing)	Tubing / 48	Intermediate	NA Casing	249 Bradenhead	1 0
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME	PRESSURES: INTERMEDIATE	CASING			BRADENHEA FLOWED	
.5 minutes	NA	249	Steady Flow		Nothing	NA
10 minutes		249	Surges			
15 minutes		249	Down to Nothin	g		
20 minutes			Nothing			
25 minutes			Gas	*****	AND 88272	
30 minutes			Gas & Water	<del>/</del>	OCT 2003	
		÷	Water			23
If bradenhead flowed water, check all of the descriptions that apply below:						
CLEAR	FRESH	SALTY	SULFUR	BI	LACK	
5 MINUTE SHUT-IN BRADENHEAD 6 INTERMEDIATE NA						
REMARKS:	ving well			**.		A A A STATE OF THE
	- went			;;;;;;;;;;		
Ву	David H	westWitz	1688			
	Pumper (Positi					