Deviation Report			
Name of Company Burlington Resources Oil & Gas Company	Address P.O. Box 4289, Farmington, NM 87499		
Lease Name and Number (API Number) SAN JUAN 28-6 UNIT #186N (30-039-29329)	Location 190 FNL 585 FEL	Sec. Twn. Rge. 06-027N-006W	
Pool and Formation Blanco Mesaverde/Basin Dakota	County RIO ARRIBA	State NEW MEXICO	

(OH)

Depth (ft)	Deviation (degrees)	
80	1.25	
99	0.50	
140	2.25	
166	0.75	450777777
200	3.25	
224	0.50	
731	1.00	To all your sales
1,233	1.00	[4 7
1,701	1.00	
2,201	1.00	FE TO THE M
2,720	1.00	The second second
3,128	1.00	- V a
3,165	1.00	W 60198
7,340	2.00	O Colins

Air Hammer Used? YES/NO

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for Burlington Resources Oil & Gas Company, am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and that the facts stated herein are true to the best of my knowledge and belief.

gliment

Subscribed and sworn to before me this 23th day of May, 2005.

Notary Public in and for San Juan County, New Mexico

My commission expires September 15, 2008.