

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-045-30342
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Burlington Resources Oil & Gas Company LP		6. State Oil & Gas Lease No.
3. Address of Operator PO Box 4289, Farmington, NM 87499		7. Lease Name or Unit Agreement Name: Allison Unit
4. Well Location Unit Letter <u>E</u> : <u>1620</u> feet from the <u>North</u> line and <u>660</u> feet from the <u>West</u> line Section <u>25</u> Township <u>32N</u> Range <u>7W</u> NMPM <u>San Juan</u> County		8. Well No. 18M
		9. Pool name or Wildcat Blanco Mesaverde/Basin Dakota
		10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

05/20/05 MIRU. Blow well down, plunger stuck in master valve on wellhead. ND WH, NU BOP. Pull donut, tag @ 8071. TOO H w/tbg. SDFWE.
05/23/05 TIH w/bailer. Bail to 8152' PBTD. TOO H. TIH w/257 jts 2 3/8" 4.7#, J-55 tbg landed @ 8047'. SN @ 8046, PBTD @ 8152'. SDFN.
05/24/05 Rig Repair. Blow well down. Land donut. ND BOP, NU WH. RD, Rig Released.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Frances Bond TITLE Regulatory Specialist DATE 5/25/05

Type or print name Frances Bond Telephone No.

(This space for State use)

SUPERVISOR DISTRICT # 3

APPROVED BY Charles TITLE

MAY 27 2005
DATE

Conditions of approval, if any: