

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

**BRADENHEAD TEST REPORT**  
(Submit 2 copies to above address)

Date of Test 3-19-05 Operator Dugan Production API # 3004525718  
Property Name Ranch Well No. 101 Location: Unit B Section 16 Township 29 Range 10 W  
Well Status (Shut-In) or Producing) Tubing 80 Intermediate \_\_\_\_\_ Casing 95 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes		<u>95</u>	Steady Flow		
10 minutes		<u>95</u>	Surges		
15 minutes		<u>95</u>	Down to Nothing		
20 minutes			<u>Nothing</u>		
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN

BRADENHEAD

0

INTERMEDIATE

N/A

REMARKS:

By

Bill Wilson

Witness

Switcher

(Position)

