NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

	F7 05			/			
Date of Test	5-5-09	Operator Dw	nan Production	<u> </u>	30045 312	270	
Property Name	State Cor	Well N	lo. 90.5 Location:	Unit Sec	ction 16 Towns	thip 32W R	ange 12h
Well Status(Sh	ut-In or Producing)	Tubing 15	Intermediate <u>N</u> A	Casing 1	Brade	~	2
	OPEN BRADE	NHEAD AND IN	TERMEDIATE TO A	TMOSDHEDE INIT	NADIAL V EC	NO 45 MINUIT	ES EACH
	01 2.1 5.0 (52		TERMILDIATE TO A	TWOSETTENE INC	NVIDUALLI PC	TO MINUT	ES EACH
	PRESSURES:			BRADENHE	AD INTER	RMEDIATE	•
TIME	INTERMEDIATE	CASING		FLOWED	FLOW	'ED	
5 mintues		0	Steady Flow	0	C)	
10 minutes	0	0	Surges	0	C		
15 minutes	0	0	Down to Nothing	0	C	>	
20 minutes	0	0	Nothing	0		2	
25 minutes	0	0	Gas			2	
30 minutes	0		Gas & Water	·		2 45553.5	12570
			Water	\bigcirc		260	
The state of the s							
If bradenhead flowed water, check all of the descriptions that apply below:							
	CLEAR	FRES	H SALTY	SULFUR	BLACK	8910	17700
	OEEAN,		JAC!	3027 01		2	
5 MINUTE S	SHUT-IN	BRADENHEAD	<u></u>	INTERMEDIATE	NATO	0	3
REMARKS:							
Blew Down to Wothing							
		V			The state of the s	(2)	- 700A
						E166.95.85 A	7337-×
					····		-
		^ 4 . /					
Ву	Michael). Bumlet		Witness			
		Switcher					
		(Position)					