

NEW MEXICO ENERGY MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District.iii/3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 06-13-03	Operator	Dominion E ; P.	API #30-0 45-	26830
Property Name Mulgo A" Well No. 12-6 Location: Unit E Section 6 Township 27 MRange 11 W				
Well Status(Shut-In or Producing) Tubing o Intermediate Casing 15 Brandenhead o				
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH				
PRESSURES: TIME INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes		Steady Flow		
10 minutes		Surges		
15 minutes		Down to Nothin	ıg	
20 minutes		Nothing		
25 minutes		Gas		
30 minutes		Gas & Water		
		Water		
If bradenhead flowed water, check all of the descriptions that apply below:				
CLEAR FRESH	SALTY	SULFUR BLA	CK C	JUL 200
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE OF DIST. 3				
REMARKS:			Well the second	Property States
Well on pump; compression				
By Dick for la	Witn	ness		
Pomper (Position)				