



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrwd.state.nm.us/ocd/District III/District.htm](http://emrwd.state.nm.us/ocd/District%20III/District.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 7-12-03 Operator MERRION OIL & GAS CORP. API #30-0 45-06138

Property Name HANSON B Well No. 2 Location: Unit K Section 36 Township 27N Range 13W

Well Status(Shut-In or Producing) Tubing 1 Intermediate NA Casing 7 Bradenhead 3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>NA</u>	<u>7</u>	Steady Flow	<u>NA</u>
10 minutes		<u>7</u>	Surges	
15 minutes		<u>7</u>	Down to Nothing <u>Down To Nothing</u>	
20 minutes		<u>7</u>	Nothing	
25 minutes		<u>7</u>	Gas	
30 minutes		<u>7</u>	Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0(TSM) INTERMEDIATE NA

REMARKS:

This is a pumpjack well with a compressor pulling on csg 1/2 mile away.
Bradenhead has been plugged above ground with 1" pipe and a valve
that has been closed and plugged all year. BH- blew down to nothing within
1 minute. After 5 minute SI the BH "whispered" a very slight
amount of dry gas.

By Scott H. Reed
Contract Engineer
(Position)

Witness _____

