



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 7-12-03 Operator MERRION OIL & GAS CORP. API #30-0 45-29837

Property Name HANSON Well No. 33 Location: Unit F Section 36 Township 27N Range 13W

Well Status(Shut-In or Producing) Tubing 1 1/2 Intermediate NA Casing 6 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>NA</u>	<u>6</u>	Steady Flow	<u>NA</u>
10 minutes		<u>6</u>	Surges	
15 minutes		<u>6</u>	Down to Nothing <u>Down To Nothing</u>	
20 minutes		<u>6</u>	Nothing	
25 minutes		<u>6</u>	Gas	
30 minutes	<u>↓</u>	<u>6</u>	Gas & Water	
			Water	<u>↓</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE NA



REMARKS:

This is a pumpjack well with a compressor pulley on the csg from
1/4 mile away. Bradenhead has been plugged aboveground with 1"
pipe and ~~plugged~~ a valve that has been shut and plugged all year.
BH. blew down to nothing within 45 seconds

By Greg J. Reid
Contract Pumping
(Position)

Witness _____