



**OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrur.d.state.nm.us/ocd/District III/3ddistrict.htm](http://emrur.d.state.nm.us/ocd/District%20III/3ddistrict.htm)**

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 6/11/03 Operator Koch Exploration Co., LLC API #30-0 45-28114

Property Name Thelma Com 33 Well No. 1 Location: Unit A Section 33 Township 28N/Range 10W

Well Status (Shut-In or Producing) Producing Tubing 32 Intermediate 32 Casing 35 Brandenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURES:		BRADENHEAD	INTERMEDIATE
TIME	INTERMEDIATE	FLOWED	FLOWED
5 minutes			
10 minutes			
15 minutes			
20 minutes			
25 minutes			
30 minutes			

Steady Flow _____

Surges _____

Down to Nothing _____

Nothing ☒

Gas _____

Gas & Water _____

Water _____

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE

REMARKS: Well has no intermediate casing

By Glen A. Huel

Witness

contract pumper
(Position)

