



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://em.nrd.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT
(Submit 2 copies to above address)

Date of Test 9/10/03 Operator ENERGEN RES. API #30-0 45-25529
Property Name Angel Peak Well No. 24 Location: Unit K Section 12 Township 28 Range 11
Pressure(Shut-In or Producing) _____ Tubing 10 Intermediate N/A Casing 25 Bradenhead 10

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>N/A</u>	<u>25</u>	Steady Flow _____	
10 minutes	<u>N/A</u>	<u>25</u>	Surges _____	
15 minutes	<u>N/A</u>	<u>25</u>	Down to Nothing ☒	
20 minutes	<u>N/A</u>	<u>25</u>	Nothing _____	
25 minutes	<u>N/A</u>	<u>25</u>	Gas ☒	
30 minutes	<u>N/A</u>	<u>25</u>	Gas & Water _____	
			Water _____	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

REMARKS:

Bradenhead blew down to nothing in 40 seconds.

By John Samyeto
Lease operator
(Position)

Witness _____

