OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

STATE OF THE PROPERTY OF THE PROPERTY OF THE BRADENHEAD TEST-REPORT OF THE PROPERTY OF THE PRO

(Submit 2 copies to above address)

Date of Test	5-14-03 o	perator <u>M&G Drilli</u>	ing Company	API #30-0	45-29116	
Property Name	e KRAUSE	Well No	24 Location: Unit A	Section 28	Township	28N Range 11W
Well Status (Sh	nut-In or Producing)	Tubing 30	Intermediate	_Casing 40	Bradenhead	Ś
OPEN	- BRADENHEAD AN	D INTERMEDIATI	E TO ATMOSPHERE	INDIVIDUALLY	FOR 15 MIN	UTES EACH
TIME	PRESSURES: INTERMEDIATE	CASING			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes		44	Steady Flow			
10 minutes			Surges			
15 minutes			Down to Nothing			
20 minutes			Nothing	<u> </u>		
25 minutes			Gas			Y(EV) DVO
30 minutes			Gas & Water			
			Water		(D) (1)	OOT 2003
If bradenhead flowed water, check all of the descriptions that apply below:						
CLEAR	FRESH	SALTY	SULFUR	BLACK		411.0
5 MINUTE SH	IUT-IN BRADENHEA	AD: <u>1.11.22</u>	INTERMEDIATE		de la compañación.	
REMARKS:			·	٠.		
•						
By	Albut Are	mala_w	itness			
	(Position)				