

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
May 27, 2004

| | | |
|---|--|--|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | | WELL API NO. <u>30-045-22434</u> |
| 1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <input type="checkbox"/> | | 5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/> |
| 2. Name of Operator BP America | | 6. State Oil & Gas Lease No. <u>SF 080597</u> |
| 3. Address of Operator 200 Energy Court Farmington NM 87401 | | 7. Lease Name or Unit Agreement Name <u>Gardner A</u> |
| 4. Well Location Unit Letter <u>C</u> : <u>1170</u> feet from the <u>North</u> line and <u>1840</u> feet from the <u>West</u> line Section <u>28</u> Township <u>30N</u> Range <u>08W</u> NMPM County <u>San Juan</u> | | 8. Well Number <u>1A</u> |
| 11. Elevation (Show whether DR, RKB, RT, GR, etc.) <u>6191 GL</u> | | 9. OGRID Number |
| Pit or Below-grade Tank Application <input checked="" type="checkbox"/> or Closure <input type="checkbox"/> | | |
| Pit type _____ Depth to Groundwater <u>> 100</u> Distance from nearest fresh water well <u>> 1000</u> Distance from nearest surface water <u>> 1000</u> | | |
| Pit Liner Thickness: _____ mil Below-Grade Tank: Volume <u>95</u> bbls; Construction Material <u>Steel</u> | | |

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

| | | | |
|---|---|--|--|
| NOTICE OF INTENTION TO: | | SUBSEQUENT REPORT OF: | |
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | P AND A <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | MULTIPLE COMPL <input type="checkbox"/> | CASING/CEMENT JOB <input type="checkbox"/> | |
| OTHER: : Below Grade Tank (With Leak Detection) <input checked="" type="checkbox"/> | | OTHER: <input type="checkbox"/> | |

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Construct a below grade tank installation per BP America - San Juan Basin Below Grade Tank Installation Plan issue date of 4/15/2004. At time of closure, below grade tank(s) will be closed according to closure plan on file.

This tank is a 95 bbl. steel double bottom double side tank.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☒, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Donald Brooks TITLE FEC DATE 6-4-05

Type or print name Donald Brooks

E-mail address: brooksd2@bp.com

Telephone No. 326-9425

For State Use Only

APPROVED BY: [Signature]

TITLE DEPUTY OIL & GAS INSPECTOR, DIST. 30

DATE JUN - 6 2005

Conditions of Approval (if any):