

NEW MEXICO ENERGY, MINIERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-4178 FAX: (505) 334-6170
http://emnrd.state.nm.ue/ocd/District HI/3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test_7	-7-03	Operator	Williams	_API #30-0 <u>39</u> ,	2335 900
Property Name Rosa Well No. 102 Location: Unit Section 30 Township3/1/Range 5W					
Well Status(Shut-In or Producing) Tubing 138 Intermediate NA Casing 187 Brandenhead O					
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH					
TIME <u>IN</u>	PRESSURES: TERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	NA	187	Steady Flow		NA
10 minutes			Surges		
15 minutes			Down to Nothing	g	
20 minutes			Nothing	0	
25 minutes			Gas	CONTRA	7/2
30 minutes			Gas & Water	16 Nov.	
			Water		
If bradenhead flowed water, check all of the descriptions that apply below:					
CLEAR FRESH SALTY SULFUR BLACK					
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE					
REMARKS: 12					
Braden head dead and dry					
	<u> </u>		<u> </u>		
By Shing Brooks Witness					