OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD

AZTEC , NM 87410 (505) 334-6178 FAX: (505) 334-6170

http://emnrd.state.nm.us/ocd/District111/3distric.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test	7/23/03	Operator RO	DBERT L. BAYLESS	API #30-0	45-09453	
Property Name	LEORA WAL	LACE Well No.	1 Location: Unit N	_Section14	Township3	ON Range 12W
Well Status (Shut-In on Producing) Tubing 280 Intermediate Casing 4/10 Brandenhead						
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME	PRESSURES: INTERMEDIATE	CASING		В.	RADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	-	460	Steady Flow			
10 minutes			Surges			
15 minutes			Down to Nothing			
20 minutes		**************************************	Nothing			
25 minutes			Gas	1 P. S.I		
30 minutes			Gas & Water		- 10 20 20 E	303773
			Water	 	bc bc	7 2000 UN
If bradenhead flowed water, check all of the descriptions that apply below:						
CLEAR	FRESE	SALTY	SULFUR	BLACK	- 1. E. O.	01.8.1
5 MINUTE SHUT-IN BRADENDHEAD INTERMEDIATE						
REMARKS:	down in	seconds				
						-
By Palmer Knopp Witness						
\subseteq	20 MPev (Positi	on)				