## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 7-16-00 Oper	rator ROBERT L. BAYLESS	API #30-0 45-10108	
Property Name STRIBLING	Well No. 1 Location: Unit _	I Section 31 Township	31N Range 13W
Well Status (Shut-In or Producing)  Tubing 320 [Status (Shut-In or Producing)  Tubing 320 [Status (Shut-In or Producing)]  Tubing 320 [Status (Shut-In or Producing)]			
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH			
PRESSURES: TIME INTERMEDIATE	CASING	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	Steady Flow		
10 minutes	Surges		
15 minutes	Down to Nothing	) <u> </u>	
20 minutes	Nothing		
25 minutes	Gas	V CO	73/123
30 minutes	Gas & Water		T 97000
	Water		· (3)
If bradenhead flowed water, check all of the descriptions that apply below:			
CLEAR FRESH	SALTY SULFUR	BLACK	
5 MINUTE SHUT-IN BRADENDHE	EAD YPS' INTERMEDIAT	E	
REMARKS: Browlen Heard Ben On in 30 Sec.			
By Witness Pumper.			
Pumber. (Position)			