

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-10-03 Operator DPK API # 30 045 - 10530
Property Name LAROSA Well No. 1 Location: Unit K Section 22 Township 31 Range 13
Well Status(Shut-In or Producing) Tubing 380 Intermediate N/A Casing 410 Bradenhead 74

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes	<u>N/A</u>	<u>410</u>	Steady Flow		
10 minutes		<u>410</u>	Surges		
15 minutes		<u>410</u>	Down to Nothing	<u>74# X</u>	
20 minutes		<u>410</u>	Nothing		
25 minutes		<u>410</u>	Gas	<u>X</u>	
30 minutes		<u>410</u>	Gas & Water		
			Water		



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 5 INTERMEDIATE _____

REMARKS:

BHD PSI 74 Blew down to nothing (gas) in 40 sec.
S/I 5 min PSI to 5# DTN in 10 sec.

By P. SIKORA Witness _____
Switcher SPV
(Position)

called 24 hour notice 7-10-03 1st msg. 5m