



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 12-12-03 Operator Pure Resources API #30-045-24504 D22

Property Name Montoya 25-1 m Well No. 25-1 m Location: Unit D Section 25 Township 32 N Range 13 W
Mesa Verde

Well Status (Shut-In or Producing) Tubing 23 Intermediate N/A Casing 80 Bradenhead 27

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>N/A</u>	<u>80</u>	Steady Flow	<u>N/A</u>
10 minutes	<u></u>	<u>80</u>	Surges	<u></u>
15 minutes	<u></u>	<u>80</u>	Down to Nothing	<u></u>
20 minutes	<u></u>	<u></u>	Nothing	<u></u>
25 minutes	<u></u>	<u></u>	Gas	<u></u>
30 minutes	<u></u>	<u></u>	Gas & Water	<u></u>
			Water	<u></u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0.0 psi INTERMEDIATE N/A

REMARKS:

Braden head flowed down to zero in 7 seconds through
a 2" valve, showed no flow for remainder of test

By Russ Knight

Witness

Mear Tech.
(Position)

