



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 5-15-03 Operator WILLIAMS E&P API #30-0 4526096

Property Name Bosa Unit Well No. 117 Location: Unit D Section 33 Township 32N Range 4W

Well Status (Shut-In or Producing) Tubing 205 Intermediate N/A Casing 209 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>N/A</u>	<u>209</u>	Steady Flow	
10 minutes			Surges	
15 minutes			Down to Nothing <u>25 sec</u>	<u>N/A</u>
20 minutes			Nothing	
25 minutes			Gas	
30 minutes			Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

Opened Bradenhead had a ~~blow~~ blew for 25 sec
and went to nothing - left valve open

By Michael A. Tech

(Position)

Witness _____

