



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnd.state.nm.us/ocd/District III/3distric.htm](http://emnd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 5/8/03 Operator WILLIAMS E&P API #30-0 4529132
Property Name Rosa Unit Well No. 88A Location: Unit L Section 8 Township 31N Range 6W
Well Status (Shut-In) or Producing Tubing 1 9/8 Intermediate N/A Casing 3/8 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>N/A</u>	<u>0</u>	Steady Flow	
10 minutes			Surges	
15 minutes			Down to Nothing	
20 minutes			Nothing	<u>N/A</u>
25 minutes			Gas	
30 minutes			Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

Opened Bradenhead no pressure
left valve open

By Michael Red

Witness _____

(Position)

