



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://emnrd.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 6-12-03 Operator WPX API #30-0 453010300

Property Name ROSA Well No. 185A Location: Unit M Section 16 Township 31N Range 6W

Well Status(Shut-In or Producing) Tubing 220 Intermediate 316 Casing 284 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>3</u>	<u>284</u>	Steady Flow	
10 minutes			Surges	
15 minutes			Down to Nothing	<u>97 sec.</u>
20 minutes			Nothing	<u>0</u>
25 minutes			Gas	
30 minutes			Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD \_\_\_\_\_ INTERMEDIATE \_\_\_\_\_

REMARKS:

Intermediate had 316. Blew down to nothing in 97 sec.  
Bradenhead had nothing (Left both Bradenhead + Intermediate open)

By

Mark Schweitzer

Witness

Tech.  
(Position)

