OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505) 334-6178 FAX: (505) 334-6170

http:\\emnrd.state.nm.us/ocd/DistrictIII/3distric.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test	7/14/03	Operator	ROBERT	L. BAYLESS, PRODUCER	<u>LLC</u> API #30-0	d <u>45-30809</u>	
Property Name	FLOYE	)	Weff No	6 Location: Unit	M Section 7	Township30	N Range 12W
Well Status (Sho	ut-In or Producing)		Tubing *	Intermediate	Casing 9	Brandenhead C	<u>)</u>
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH							
TIME	PRESSURES: INTERMEDIATE	2	CASING		***************************************	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes				Steady Flow			
10 minutes			<del></del>	Surges			
15 minutes		9		Down to Nothing	-		
20 minutes			·	Nothing		2000	
25 minutes				Gas	<i>k</i>	007 8013	
30 minutes				Gas & Water			- <del> </del>
				Water	/:		
If bradenhead flowed water, check all of the descriptions that apply below:							
CLEAR	FRESI	Ŧ	SALTY	YSULFUR	BLACK		
5 MINUTE SHUT-IN BRADENDHEAD INTERMEDIATE							
REMARKS:	ducing	UP G	c <u>asi</u> ,	n 9		. 77 1977	
				- 111-111-111-111-111-111-111-111-111-1			
By Q	Imav K	nept	2 ,	Witness			
	(Positi	on)					