



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emrmd.state.nm.us/ocd/District III/district.htm](http://emrmd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 4-28-03 Operator DJ Simmons API #30-0 45 07891

Property Name Simmons Well No. S-1 Location: Unit    Section 25 Township 29<sup>N</sup> Range 9<sup>W</sup>

Well Status(Shut-In or Producing)    Tubing 136 Intermediate 72 Casing 150 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

| TIME       | PRESSURES:   |            | BRADENHEAD<br>FLOWED | INTERMEDIATE<br>FLOWED |
|------------|--------------|------------|----------------------|------------------------|
|            | INTERMEDIATE | CASING     |                      |                        |
| 5 minutes  |              | <u>150</u> | Steady Flow          | <u>slight</u>          |
| 10 minutes |              | <u>150</u> | Surges               |                        |
| 15 minutes |              | <u>150</u> | Down to Nothing      |                        |
| 20 minutes |              |            | Nothing              | <u>X</u>               |
| 25 minutes |              |            | Gas                  | <u>X</u>               |
| 30 minutes |              |            | Gas & Water          |                        |
|            |              |            | Water                |                        |

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR    FRESH    SALTY    SULFUR    BLACK   

5 MINUTE SHUT-IN BRADENHEAD    INTERMEDIATE   

REMARKS:

Strong Intermediate first 2 min. flow down to not able  
to be heard at 5 min but felt by hand  
at 10 min. Slight flow could be heard thru  
1/4" bushing

By K. W. [Signature]  
Field Tech  
(Position)

Witness   

