



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://emvrd.state.nm.us/ocd/District/III/3district.htm>

**BRADENHEAD TEST REPORT**

(submit 2 copies to above address)

Date of Test 4-28-03 Operator D J Simmon API #30-0 45 22 802

Property Name Simmons Well No E-2-A Location: Unit      Section 23 Township 29<sup>N</sup> Range 9<sup>W</sup>

Well Status(Shut-In or Producing) Tubing 190 Intermediate 120 Casing 190 Bradenhead 4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

| TIME       | PRESSURES:   |            | BRADENHEAD FLOWED | INTERMEDIATE FLOWED |
|------------|--------------|------------|-------------------|---------------------|
|            | INTERMEDIATE | CASING     |                   |                     |
| 5 minutes  | <u>120</u>   | <u>190</u> | Steady Flow       |                     |
| 10 minutes | <u>120</u>   | <u>190</u> | Surges            |                     |
| 15 minutes | <u>120</u>   | <u>190</u> | Down to Nothing   | <u>X</u>            |
| 20 minutes |              |            | Nothing           |                     |
| 25 minutes |              |            | Gas               | <u>X</u>            |
| 30 minutes |              |            | Gas & Water       |                     |
|            |              |            | Water             |                     |

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR      FRESH      SALTY      SULFUR      BLACK     

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Bradenhead blew down rapidly - slight  
sound when valve was opened  
Intermediate blew strong for 2 min. Still could  
hear blow at 5 min. nothing at 10 min. no sign

By K Marchese

Witness     

Field Tech

(Position)

of flow thru 1/4" bushing at 15 min

