

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

**BRADENHEAD TEST REPORT**  
(Submit 2 copies to above address)

Date of Test 5-20-03 Operator Dugan Production Corp. API # 30-045-30732  
Property Name RIVIERA COM Well No. 2 Location: Unit E Section 18 Township 30N Range 14W  
Well Status(Shut-In or Producing) \_\_\_\_\_ Tubing 20 Intermediate \_\_\_\_\_ Casing 20 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes			Steady Flow		
10 minutes			Surges		
15 minutes			Down to Nothing		
20 minutes			Nothing	✓	
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN**

BRADENHEAD \_\_\_\_\_

INTERMEDIATE \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By

Ken Rutecki

Witness \_\_\_\_\_

51

Switcher  
(Position)

