



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.ornrd.state.nm.us/aztec/District3/azteprec3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-14-05 Operator R.C. Resources API # 30-0.45-24246
Property Name Taliaferro Well No. 5M Location: Unit I Section 30 Township 31N Range 12W
Well Status (Shut-In or Producing) Tubing 71 Intermediate 193 Casing 193 Bradenhead 160

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>puff to 0</u>		<u>193</u>	Steady Flow	
10 minutes	<u>0</u>		<u>193</u>	Surges	
15 minutes	<u>0</u>		<u>193</u>	Down to Nothing	<u>X</u>
20 minutes				Nothing	
25 minutes				Gas <u>X</u>	
30 minutes				Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 4 psi INTERMEDIATE

REMARKS:

Could see gas flames coming out of bradenhead
Braden head blew out black foam probably from seeping well
Bradenhead blew down in less than 20 sec.

By

Jenny Dume

Witness

Operator
(Position)

E-mail address