Deviation Report

Name of Company Burlington Resources Oil & Gas Company	Address P.O. Box 4289, Farmington, NM 87499	
Lease Name and Number (API Number) SAN JUAN 27-5 UNIT #108N (30-039-26933)	Location -1690 FSL -1905 FWL	Sec. Twn. Rge. 15-027N-005W
Pool and Formation Blanco Mesaverde/Basin Dakota	County RIO ARRIBA	State NEW MEXICO

(OH)

Depth (ft)	Deviation (degrees)	
60	0.50	
120	0.50	
140	0.50	0 0 10
614	0.50	61091011
1,115	0.50	(A) (A)
1,609	0.50	JUN 2000
2,076	0.50	JUN 2003 S
2,545	0.50	OIL CONS
3,045	0.50	
3,722	0.50	DIST. 3
7,974	0.50	E 22 27 12 13 13 13 13 13 13 13 13 13 13 13 13 13
		The state of the s

Air Hammer Used?(YES// NO

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for Burlington Resources Oil & Gas Company, am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and that the facts stated herein are true to the best of my knowledge and belief.

Erin J. Hiles

Subscribed and sworn to before me this 22th day of April, 2003.

Notary Public in and for San Juan County, New Mexico

My commission expires September 15, 2004.