


Deviation Report

Name of Company Burlington Resources Oil & Gas Company	Address P.O. Box 4289, Farmington, NM 87499	
Lease Name and Number (API Number) SAN JUAN 28-6 UNIT #185N (30-039-27658)	Location -1925 FSL 1970 FEL	Sec. Twn. Rge. 33-028N-006W
Pool and Formation Blanco Mesaverde/Basin Dakota	County RIO ARRIBA	State NEW MEXICO

(OH)

<u>Depth (ft)</u>	<u>Deviation (degrees)</u>
145	0.00
640	1.00
1,109	1.00
1,609	1.00
2,109	1.00
2,596	1.00
3,094	1.00
3,594	1.00
3,595	0.50
7,765	0.75



Air Hammer Used? YES NO

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for Burlington Resources Oil & Gas Company, am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and that the facts stated herein are true to the best of my knowledge and belief.

A handwritten signature in black ink, appearing to read "Frances S. Dand", written over a horizontal line.

Subscribed and sworn to before me this 18th day of July, 2005.

A handwritten signature in black ink, appearing to read "Frances S. Dand", written over a horizontal line.

Notary Public in and for San Juan County, New Mexico

My commission expires September 15, 2008.