



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT


(Submit 2 copies to above address)

Date of Test 8-26-05 Operator Devon Energy API #30-0 45-28553
Property Name NEBU Middle Mesa SW Well No. #2 Location: Unit 11 Township 31N Range 07W
Well Status (Shut-In or Producing) 350 Tubing 350 Intermediate N/A Casing 8 Bradenhead 1.6

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		
	BRADENHEAD	INTERMEDIATE	CASING
5 minutes	0		9
10 minutes	0		9
15 minutes	0		9
20 minutes			
25 minutes			
30 minutes			

	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
Steady Flow		
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE N/A

REMARKS: Blew down to nothing in 10 seconds
took off a tank & went straight into casing. Gauge showed 9

By Kenneth W. Langhin
Contractor ARK Sales & Service
(Position)

Witness

Monica Kuhlberg

E-mail address _____