

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(505) 334-6178

FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 12-7-04	Operato	or BC+D Operating	_API #30-0_31 -	-05214
Property Name Haspah Sand	UNIT Well No.#	27 Location: Unit P	Section <u>36</u> Towns	hip <u>18 </u>
Well Status (Shut-In)or Produ	ncing) Tubing	Intermediate None Cas	sing Praden	head 👝
OPEN BRADENHEAD ANI	D INTERMEDIATE	TO ATMOSPHERE INDI	VIDUALLY FOR 1	5 MINUTES EACH
PRES TIME <u>BRADENHEAD</u> INT	SURES: ERMEDIATE CASI	ŃG_	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes	NONE &	Steady Flow		
10 minutes		Surges		
15 minutes		Down to Noth	ing	
20 minutes 6	- 6	Nothing		NONE
25 minutes		Gas	· · · · · · · · · · · · · · · · · · ·	
30 minutes		Gas & Water_		
		Water		
If bradenhead flowed water, check all of the descriptions that apply below:				
CLEAR FRESH	HSALTY_	SULFUR BLA	CK	
5 MINUTE SHUT-IN BRAD REMARKS:	ENHEAD	INTERMEDIATE	·	
				The state of the s
By Att Interven	,	Witness		
(Position) 3-mail address				