



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 9.2.05 Operator Burlington API #30-0 39-07712
Property Name San Juan 306 Well No. 31 Location: Unit 33 Section 33 Township 30 Range 6
Well Status (Shut-In or Producing) Producing Tubing 175 Intermediate 175 Casing 179 Bradenhead 16

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes			<u>179</u>	Steady Flow	
10 minutes			<u>178</u>	Surges	
<u>14</u> 15 minutes			<u>177</u>	Down to Nothing	
20 minutes	<u>0</u>		<u>175</u>	Nothing	
25 minutes	<u>0</u>		<u>173</u>	Gas	
30 minutes	<u>0</u>		<u>172</u>	Gas & Water	
				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS: Blow down in 14 minutes
well ceasing flow

[Signature]
Operator
(Position)

Witness Monica Lucking

E-mail address _____

