

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 9-2-05 Operator Burlington API #30-0 39-25620
Property Name San Juan 30-6 Well Well No. 31A Location: Unit _____ Section 33 Township 30N Range 06W
Well Status (Shut-In or Producing) Producing Tubing 138 Intermediate 14 Casing 148 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURES:				BRADENHEAD		INTERMEDIATE	
TIME	BRADENHEAD	INTERMEDIATE	CASING	FLOWED	FLOWED	FLOWED	FLOWED
5 minutes				Steady Flow			
10 minutes				Surges			
15 minutes				Down to Nothing			
20 minutes				Nothing			
25 minutes				Gas			
30 minutes				Gas & Water			
				Water			

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE

REMARKS: Walking on beach head.

By 
 Lease Operator
 (Position)

Witness Monica Ruchling

E-mail address _____