

Deviation Report

Name of Company

Burlington Resources Oil & Gas Company

Address

P.O. Box 4289, Farmington, NM 87499

Lease Name and Number (API Number)

SAN JUAN 28-6 UNIT #115P (30-039-29478)

Location

-2610 FSL -1335 FWL

Sec. Twn. Rge.

03-027N-006W

Pool and Formation

Blanco Mesaverde/Basin Dakota

County

RIO ARRIBA

State

NEW MEXICO

(OH)


Depth (ft)**Deviation (degrees)**

90	1.00
180	1.00
270	0.50
345	0.50
856	1.00
1,356	1.00
1,859	1.00
2,351	1.00
2,845	1.00
3,640	1.00
7,785	2.00

Air Hammer Used? YES/ NO

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for Burlington Resources Oil & Gas Company, am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and that the facts stated herein are true to the best of my knowledge and belief.

Subscribed and sworn to before me this 08th day of September, 2005.



Notary Public in and for San Juan County, New Mexico

My commission expires September 15, 2008.

