

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT
(Submit 1 copy to above address)

OIL CONS. DIV DIST. 3

NOV 01 2012

Date of Test 5-23-12 Operator Dugan Production Corp. API # 30-045-33186
Property Name BITSILI Well No. 1 Location: Unit G Section 19 Township 24N Range 9W
Well Status(Shut-In or Producing) Initial PSI: Tubing 35 Intermediate 1/A Casing 30 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		30			
10 minutes	0		30			
15 minutes	0		30			
20 minutes	0		30			
25 minutes	0		30			
30 minutes	0		30			

FLOW CHARACTERISTICS

Steady Flow
Surges
Down to Nothing
Nothing
Gas
Gas & Water
Water

BRADENHEAD	INTERMEDIATE
X	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD X INTERMEDIATE _____

REMARKS:

By Mike S. [Signature]
Switcher
(Position)

Witness _____