

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

<http://emnr.state.nm.us/ocd/District/III/3district.htm>

**BRADENHEAD TEST REPORT**

(Submit 1 copy to above address)

**OIL CONS. DIV DIST. 3**

**NOV 01 2012**

Date of Test 5-23-12 Operator Dugan Production Corp. API # 30-045-33186  
Property Name BITSILI Well No. 1 Location: Unit G Section 19 Township 24N Range 9W  
Well Status(Shut-In or Producing) Initial PSI: Tubing 35 Intermediate NA Casing 30 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

TIME	Bradenhead			Interm		
	BH	Int	Csg	Int	Csg	
5 minutes	0		30			
10 minutes	0		30			
15 minutes	0		30			
20 minutes	0		30			
25 minutes	0		30			
30 minutes	0		30			

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X	
Nothing		
Gas		
Gas & Water		
Water		

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN**

BRADENHEAD

X

INTERMEDIATE

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By

Mike Sneed  
Switcher  
(Position)

Witness

\_\_\_\_\_