



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

Due 10/22/12

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OCT 30 2012

Date of Test 10-10-12 Operator Elm Ridge API #30-0 45-33718
Property Name Turtle Mt 35 Well No. 2 Location: Unit K Section 35 Township 24N Range 8W
Well Status(Shut-In or Producing) Initial PSI: Tubing P Intermediate None Casing P Bradenhead SI

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0		94		
10 min	0		94		
15 min	0		94		
20 min	0		94		
25 min	0		94		
30 min	0		94		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

No pressure / No vacuum on Braden Head.
Shut in 24 hrs before test

By Lee Ingram
Lease Operator
(Position)

Witness _____

E-mail address _____