



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

* Due 10/22/12

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

OCT 30 2012

(submit 1 copy to above address)

Date of Test 7-10-12 Operator Elm Ridge API #30-0 45 25244

Property Name Dome Fed 24 Well No. 21 Location: Unit C Section 24 Township 3N Range 8

Well Status(Shut-In or Producing) Initial PSI: Tubing SI Intermediate None Casing SI Bradenhead SI

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead		INTERM			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	0		12			Steady Flow	
10 min	0		12			Surges	
15 min	0		12			Down to Nothing	
20 min	0		12			Nothing	✓
25 min	0		12			Gas	
30 min	0		12			Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

No pressure / No vacuume on Braden Head
Shut in over 24 hrs before test
Well shut in / Hole in tubing / Needs Rig work

By Lee Ingram

Witness _____

Lease Operator
(Position)

E-mail address _____