



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

Oil Cons. Div
District III

BRADENHEAD TEST REPORT

SEP 05 2012

(submit 1 copy to above address)

Date of Test 8/27/2012 Operator Black Hills API #30-0 39-29314
Property Name 2. C 458-5 Well No. 22 Location: Unit Section 5 Township 30N Range 3W
Well Status (Shut-In or Producing) Initial PSI: Tubing 26 Intermediate 0 Casing 311 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	306	0	305
10 min	0	0	306	0	305
15 min	0	0	305	0	305
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	☒	
Nothing		
Gas	☒	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS: Braden head nothing, Intermediate was
zero on guage & second pool down to nothing

By Robert Talamante Witness
lease operator
(Position)

E-mail address

JP
ca