



**OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emrwd.state.nm.us/ocd/District/II/3distric.htm>**

OIL CONS. DIV DIST. 3

OCT 02 2012

(submit 1 copy to above address)

Date of Test 9-20-22 Operator Chavon API #30-039-06539

Property Name Rincon Well No 93 Location: Unit Section 11 Township 26 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing 6 Intermediate N/A Casing 6.6 Bradenhead 8

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	1	6.6		
10 min	0	1	6.6		
15 min	0	1	6.6		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 

INTERMEDIATE *N/A*

REMARKS:

REMARKS: no PSI on BLEAD, Replaced valve,

By Randy Culcote

Witness

Golden Service
(Position)

E-mail address Randy.c@calderservice.com

ca