NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

OIL CONS. DIV DIST. 3

OCT 0 2 2012

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-20-12 Operator Chevron API #30-039-06596

Property Name Rincon Well No 92 Location: Unit ___ Section 11 Township 26n Range 7w

Well Status(Shut-In or Producing) Initial PSI: Tubing 30 Intermediate N/A Casing 36.3 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME 5 min	0		36.3		
10 min	0		36.3		
15 min	0		36.3		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR_____ FRESH_____ SALTY_____ SULFUR_____ BLACK_____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD Ø INTERMEDIATE N/A

REMARKS: No Pressure in Bradenhead, Replaced valve

By Randy Culcote Witness_____

Calder Service
(Position)

E-mail address Randy.c@calderservice.com

Ca