



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdd.state.nm.us/ocd/District III/district.htm](http://emrdd.state.nm.us/ocd/District%20III/district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OCT 02 2012

Date of Test 9-20-12 Operator Chevron API # 30-039-06625

Property Name Rincon UNIT Well No 96 Location: Unit Section 12 Township 26N Range 7W

Well Status (Shut-In or Producing) Initial PSI: Tubing 24.9 Intermediate N/A Casing N/A Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	<u>0</u>	<u> </u>	<u>N/A</u>	<u> </u>	<u> </u>	Steady Flow	
10 min	<u>0</u>	<u> </u>	<u>N/A</u>	<u> </u>	<u> </u>	Surges	
15 min	<u>0</u>	<u> </u>	<u>N/A</u>	<u> </u>	<u> </u>	Down to Nothing	
20 min						Nothing <u>X</u>	
25 min						Gas	
30 min						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS: CSS valves wont open unable to check CSS PSI

By Randy Culcote

Witness

Culder service
(Position)

E-mail address Randy.C@culderservice.com