



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emrds.state.nm.us/ocd/District/III/3district.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT
(submit 1 copy to above address)

OCT 02 2012

Date of Test 9-20-12 Operator Chauver API #30-039-06648

Property Name Pincon Well No 11 Location: Unit Section 6 Township 26 Range 6W

Well Status (Shut-In or Producing) Initial PSI: Tubing 65 Intermediate Ø Casing 60 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>Ø</u>	<u>Ø</u>	<u>60</u>	<u>Ø</u>	<u>60</u>
10 min	<u>Ø</u>	<u>Ø</u>	<u>60</u>	<u>Ø</u>	<u>60</u>
15 min	<u>Ø</u>	<u>Ø</u>	<u>60</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>X</u>	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Ø INTERMEDIATE Ø

REMARKS:

Buried valve on Bhead compressed open Intermediate valve, Replaced AFTER Test

By Randy Culcote

Witness

Culder service
(Position)

E-mail address Randy.C@culderservice.com

ca