



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdd.state.nm.us/ocd/District III/district.htm](http://emrdd.state.nm.us/ocd/District%20III/district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OCT 02 2012

Date of Test 9-20-12 Operator Chevron API # 30-039-21829

Property Name Rincon Well No 231 Location: Unit 12 Section 12 Township 26 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 2.1 Intermediate N/A Casing 2.5 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			FLOW CHARACTERISTICS	
	BRADENHEAD			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	1	2.5		
10 min	0	1	2.5		
15 min	0	1	2.5		
20 min					
25 min					
30 min					

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

no pressure on Braden Head, Replace valve, upper valve was closed when arrived.

By Randy Culcote

Witness _____

Culder service
(Position)

E-mail address Randy.C@culderservice.com

ca