



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrmd.state.nm.us/ocd/District 11/3d1stric.htm](http://emrmd.state.nm.us/ocd/District%2011/3d1stric.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OCT 02 2012

Date of Test 9-24-12 Operator Chewon API #30-039-24688

Property Name Rincon Well No 276 Location: Unit 13 Section 13 Township 27 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 23.1 Intermediate n/a Casing 27 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead		Int	Csg
		Int	Csg		
TIME					
5 min	Ø		26.9		
10 min	Ø		26.9		
15 min	Ø		26.4		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Ø

INTERMEDIATE n/a

REMARKS:

By Randy Culcote

Witness _____

Culder Service
(Position)

E-mail address Randy.C@calderservice.com

Ca