



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 1-30-13 Operator ConocoPhillips API #30-0 45-35383

Property Name Yert HZMC Well No. 1H Location: Unit B Section 36 Township 29 Range 10

Well Status (Shut-In or Producing) Initial PSI: Tubing 962 Intermediate 901 Casing 967 Bradenhead 121
395

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	Bradenhead			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min	0	42	901.8	0	894	965
10 min	0	41	901.7	0	893	
15 min	0	41	901.9	0	893	966
20 min						
25 min						
30 min						

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	/	/
Nothing		DIST. 3
Gas		/
Gas & Water	/	OIL CONS. DIV.
Water		RCVD JAN 30 '13

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 10

INTERMEDIATE 1.9

REMARKS:

BH - flow did not make it to Pit - 88 feet.
Int. dead at 9 seconds - 2nd Int. fell to 894 -

By [Signature]
FDT mso
(Position)

Witness Monica Kuehling
Re-test in 30 days.
Bleed into bucket

E-mail address _____