



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

## MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 2-14-13 Operator HPOC, LLC API # 30-0 31-21112

Property Name Ojo Encino 31 Fed Well # 1 Location: Unit B Sec 31 Twn 20 Rge 5

Land Type:

State \_\_\_\_\_  
Federal \_\_\_\_\_  
Private \_\_\_\_\_  
Indian /

Well Type:

Water Injection \_\_\_\_\_  
Salt Water Disposal /  
Gas Injection \_\_\_\_\_  
Producing Oil/Gas \_\_\_\_\_  
Pressure observation \_\_\_\_\_

Temporarily Abandoned Well (Y/N) (N) TA Expires: \_\_\_\_\_

Casing Pres. 100 Tbg. SI Pres. \_\_\_\_\_ Max. Inj. Pres. \_\_\_\_\_  
Bradenhead Pres. 8 Tbg. Inj. Pres. \_\_\_\_\_  
Tubing Pres. 8  
Int. Casing Pres. N/A

Pressured annulus up to 500 psi. for 30 mins. Test passed/failed (failed)

### REMARKS:

Driller Det - 5762 - 5773 DIST. 3  
for Driller - 5810 OIL CONC. DIV.

RCVD FEB 14 '13

All Check required before injection

By [Signature] (Operator Representative) Witness [Signature] (NMOCD)

Consultant  
(Position)

Revised 02-11-02

