



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emhnd.state.nm.us/ocd/District10/District.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT
(submit 1 copy to above address)

MAR 06 2013

Date of Test 2-28-13 Operator Chevron midcont API #30-03206988

Property Name Rincon Well No. 120 Location: Unit E Section 22 Township 27 Range 6W

Well Status (Shut-In or Producing) Initial PSI: Tubing 39 Intermediate X Casing 79 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		79		
10 min	0		79		
15 min	0		79		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE X

REMARKS:

By Randy calder
calder services
(Position)

Witness _____

E-mail address Randy.c@calderservices.com

3-4-13