



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://famr.nd.state.nm.us/ocd/District1103/district.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

MAR 06 2013

Date of Test 3-4-13 Operator Chavira midcowT API #30-039-22311

Property Name Rincon Well No. 21 A Location: Unit L Section 16 Township 27 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 64 Intermediate X Casing 70 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE Bradenhead			INTERM		
	BH	Int	Csg	Int	Csg	
5 min	0		70			
10 min	0		70			
15 min	0		70			
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE X

REMARKS:

By Randy calder
calder services
(Position)

Witness _____

E-mail address Randy.c@calderservices.com

3-5-12