



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6170 FAX: (505) 334-6170
<http://enrard.state.nm.us/ocd/District103/district.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

MAR 13 2013

Date of Test 3-7-13 Operator Chelva midcoast API #30-0 39-06945

Property Name Rincon Well No. 170 Location: Unit 11 Section 20 Township 27 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 39 Intermediate X Casing 56 Bradenhead 3

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	0		55		
10 min	0		54		
15 min	0		53		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X	
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE X

REMARKS: Bradenhead Blew down to nothing in 20 sec, then dead for
Remarks of Test

By Randy calcote
calder services
(Position)

Witness _____

E-mail address Randy.c@calderservices.com

3-12-13